
City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 1 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: <u>12/04/2008</u>
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S05YY_003MH	Test ID: S1032-026029	Notifications (Residents, Fire, 311) : Yes


Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 2 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date : <u>12/04/2008</u>
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S05YY_003MH	Test ID: S1032-026029	Notifications (Residents, Fire, 311) : Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Downspout Connection; Smoke: Medium; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Service Lateral; Smoke: Heavy; Status: Private Property

Landscape




Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 3 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date : <u>12/04/2008</u>
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S05YY_003MH	Test ID: S1032-026029	Notifications (Residents, Fire, 311) : Yes

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property

Defect



Landscape




Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 4 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date : <u>12/04/2008</u>
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S05YY 003MH	Test ID: S1032-026029	Notifications (Residents, Fire, 311) : Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Downspout Connection; Smoke: Medium; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Catch Basin; Smoke: Heavy; Status: Public ROW

Landscape



Defect

